Subject: Actual fuel quantity Posted by Anonymous on Mon, 28 Jul 2014 21:35:57 GMT View Forum Message <> Reply to Message

I've seen the same on the outers on the 15gal variety, my 35 gal outers seem to drain fully. Always had very good accuracy on the foxboro.

Page 1 of 1 ---- Generated from MU-2 Owners and Pilots Group