
Subject: Sperry gyros, HSIs and Sperry FD ADI
Posted by [Mike Rapoport](#) on Thu, 31 Mar 2022 00:00:43 GMT
[View Forum Message](#) <> [Reply to Message](#)

Removed during dual G600 install

2 C-14A gyros
1 VG-14A gyro
1 RD-444 HSI
1 RD-44 HSI
1 HZ-454 ADI (single que)

All working properly when removed

\$500ea plus actual shipping cost
